






FIG. 5

















FIG. 10




FIG. 11A




FIG. 11B




FIG. 11C




FIG. 11D





FIG. 11E







FIG. 13



A'

14/19

FIG. 15




FIG. 16




FIG. 17

URL http://www.maintain.co.jp/db/input.html	
TROUBLE DB INPUT WINDOW	
-	
OCCURRENCE DATE 2000/3/15 4040	
TYPE OF APPARATUS ******** ~4010	
SUBJECT OPERATION ERROR (START-UP ERROR) ~4030	
SERIAL NUMBER S/N 465NS4580001 ~4020	
DEGREE OF URGENCY D ~4050	
SYMPTOM	LED IS KEPT FLICKERING AFTER 企
	POWER-ON 4060
REMEDY	POWER ON AGAIN
	(PRESS RED BUTTON IN ACTIVATION) 4070
PROGRESS	INTERIM HAS BEEN DONE 位
	4080
(SEND) (RE	
LINK TO RESULT LIST DATABASE SOFTWARE LIBRARY OPERATING GUIDE	

FIG. 18




FIG. 19

